



CERTIFICATE OF STRUCTURAL SAFETY

(To be jointly signed by an Empanelled Structural Engineer and Owner of the building)


The following certificate is submitted after site visit and proper investigations for **St. Mark's Senior Secondary Public School B-Block, Nilothi-Meera Bagh Rd, Block-8, Meera Bagh, Paschim Vihar, New Delhi-110087.**

- (i) Certified that this structural stability certificate has been issued after taking into consideration
 - a) The National Building Code of India, including the structural design of foundation masonry, timber, plain, concrete, reinforced concrete, pre-stressed concrete and structural steel shall be carried out in accordance with Part-VI structural design, section-1 loads, section-2 foundation, section-3 wood, section-4 masonry, section-5 concrete and section-6 steel of National Building Code, and
 - b) All relevant standards prescribed by Bureau of Indian Standards including the standard given in Is-Code 13920-2016, 4326-1993, 13828- 1998, 13827-1993, 13935-1993, 456:2000, 800-1984, 801-1975, 875 (Part-2):1987,875 (Part-3): 1987-875 (Part4): 1987-875 (Part5): 1987, 883:1966, 1904:1987, 1905:1987, 2911 (Part I): Section I: 1979, 1893-2002 for general structural safety, cyclone/ wind protection, earthquake protection.
- (ii) Certified that the above-mentioned building [including tangible items on its rooftops, such as Water storage capacity, etc.] existing as on date, fulfill all the structural safety requirements.


SIGNED BY: 
 Signature of Structural Engineer
 Name of Structural Engineer **Ajay Agrawal**
 Address of Structural Engineer **D-196, Saket**
 License / Empanelment No. **SE-0026**
 Date **16/7/21**

For St. Marks Sr. Sec. Public School
 Signature of Owner(s) 
 Name of Owners(s) **Meera Bagh**
 Address of Owners(s) _____ Chairman
 Date **16/7/21**

- In addition to the certification given at Sl. No (i) and (ii) above, it is also certified that:
- (iii) Any tangible item on the rooftop of the above-mentioned building (existing as on date), such as Telecom Tower(s), DG sets, Water storage capacity, Air conditioning units, etc., are in accordance with the necessary permissions / clearances etc.
 - (iv) The owner(s) of the above-mentioned building undertakes that they shall be liable for all criminal and/or civil liability(s) arising out of non-adherence to the statutory compliances, including structural safety of the building.

For St. Marks Sr. Sec. Public School
 SIGNED BY: 
 Signature of Owner(s)
 Name of Owners(s) _____ Chairman
 Address of Owners(s) _____
 Date **16/7/21**

ST. MARKS SR. SEC. PUBLIC SCHOOL,
 A-BLOCK, MAIN ROAD,
 MEERA BAGH, NEW DELHI-110087



Mrs. RITIKA ANAND
 PRINCIPAL
 St. Mark's Sr. Sec. Public School
 A-Block, Meera Bagh,
 New Delhi-110087