

B5.



Kapisur's

arun singhal


Architects, Engineers
& Project Planner

306, Pocket A-3, Sector-8,
Rohini, Delhi-110085
Ph. : 9810170499
GSTIN : 07AATPS4071N1ZU

STRUCTURE STABILITY CERIFICATE


This is to certify that structural parts of existing school building of St mark's Girls Senior secondary School situated at A block Meera Bagh New Delhi 110087 belonging to St Mark's Christian Educational Society Janak Puri New Delhi 110058 are analysed on the basis of calculation and considered to be safe & sound.

It is also certified that the structural parts are analysed keeping in consideration the safety from natural hazard based on soil condition and also as per national Building Code 2005 and building is ready for occupation.


31/07/19 AR. ARUN SINGHAL
CA/84/8218
306, Pocket A-3, Sec-8
Rohini, Delhi-110085
Architect

Arun Kumar Singhal

CA/1984/08218


MS. SHEENA KALENGA
Principal
St. Mark's Girls Sr. Sec. School
Meera Bagh, New Delhi-110087